Work Orde Tuesday, July 29				*123	3046*						Page 1
Item ID: Revision ID: Item Name:	D3589-15			Accept	*N900	04 0	100) *	Setup Sta		S1* S2*
Start Date: Required Date: Reference:	7/29/14	Start Qty: 4.00 Req'd Qty: 4.00	*4* *4*		Cust Item I Customer:	D:					.7/
Approvals:	Process Pl	an: TA	Date: 14/07/	20 Taaling:	D:	ate:	_	F	Run Sta	^{rt} *N	R1*
Approvais.	QC:	un. <u>/ U</u>	Date:	SPC (Y/N):		ate:			Sto	*N	R2*
Sequence ID/ Work Center II	D ,	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Re	vision Nbr		1,00							
D3589	С										
100				0.00						,	1 1
*1 \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\	jet	Memo Cut as per d Prog Rev:_ Dwg Rev:_ Deburr as re	<u>C</u>	0.00				(13)		2/De	<u> 14/04/11</u>

0.00

0.00

QC2- Inspect parts off machine FAI/FAIB

Memo

110

*11**0***

Quality Control

DQA:			Date:			•							"DART
						WORK ORDER NON	-CC	ONFO	RMANCE / UP				AEROSPACE
QA Closed:			Date:							V	Vork Order up	date only	
Work Orde	ır.					DISPOSITION				AGAINST D	EPARTMENT	/PROCESS	
VVOIR OIGC	-				-	Rework	7		Skid-tube	Crosstube	7	Water Jet	Engineering
Part N	lo.					Scrap	1		Machining	Small Fab	Pro	d. Eng. Coor.	Quality
	٠	*				Use-as-is	1	Therr	moforming	Finishing	Rec/Sto	re/Packaging	Other
NCR N	lo.					Suspected Unapproved]		Large Fab	Composite		Supplier	
			7			·	$\overline{}$		Acti		Cian 9		
Root			_c ,	0.	Desci	ription of work order update	i i	nitial	1		Sign & Date	Verification	QC Inspector
Cause	_	Date	Step	Qty	-	or non-conformance	Ch	ief Eng	Descri	ption	Date	vernication	QC IIISPECTOI
Design	-											1	
Doc/Data													
Equip/Tooling Handling/Pre	\dashv												
Material	\dashv												
Operator	-												
Offset/Setup					ļ								
Process							1						
Supplier	\exists		<u>[</u>										
Training													
Transport													
Unapproved												<u> </u>	
							FA	ULT CA	TEGORY	· · · · · · · · · · · · · · · · · · ·			
Landii	ng (Gear				General	_	,		_	 1	_	 1
, .	i	Bending				Bend		Folio/I	Program	_	Outside Dim	—	Pressure/Forced
		Centre N	ot Concer	ntric		BOM/Route		Grain			Over/Under	 	Set-up
		Cracks			_	Broken/Damage/Defect	_	Hardwa		ļ	Part Incorre	├	Temperature/Cure
		Crimp/Ki	nk/Ripple	/Wave	<u> </u>	Burrs	_	4 ·	tion Incomplete/Un	· -	Part Lost/M	· ·	Weld
		Cuffs				Contamination	_	-1	tions Incomplete/U	Inclear	Part Moved	_	Wrong Stock Pulled
		Crushing			<u> </u>	Countersink	<u> </u>	-	gned/off center	-	Positioned \		7 045 - 11
	<u> </u>	Heat Tre			<u> </u>	Cut Too Short	<u> </u>	Mislab		L	Power Loss/	Surge	Other
		1	n Strip in	Tube	<u> </u>	Drawing	<u> </u>	Misrea					
	<u> </u>	Marks/Cl			<u> </u>	Drill Holes	-	Off-set					
	<u> </u>	4	Sequence			Finish	\vdash		Calibration		 		
	<u> </u>	Wave/Tv	vist in Tub	oe .		Fit/Function		Out of	Sequence				

Work Ord Tuesday, July 29				*123	3046*						Page 2	
Item ID: Revision ID: Item Name:	D3589-15	·		Accept	*N900	<u>040</u>	100)* s	Setup Sta	17	S1* S2*	
Start Date: Required Date: Reference:	7/29/14 7/29/14	Start Qty: 4.00 Req'd Qty: 4.00	*4 *4		Cust Item I Customer:	D:						
Approvals:		nn:	Date:	Tooling: SPC (Y/N):		ate:		F	Run Sta Sto	n ^I√I	R1* R2*	
Sequence ID/ Work Center II 120 *1 20* QC Quality Control 140 *1 40* Packaging Packaging	D	Operation Description QC8- Inspect parts - second Memo Identify as per dwg & St Memo		Set Up/ Run Hours 0.00 0.00	Tool ID	Tool#	Plan Code	Accept Qty 13	Reject Qty	Reject Number	1-9-1	
*150 *150* QC Quality Control		QC21- Final Inspection Memo	- Work Order Relea:	ose 0.00 0.00					14	19/16	MF O	+ 1-15

DQA:			Date:		-								DART
			. .			WORK ORDER NON	l-CC	ONFO	RMANCE / UI		- ul. Oud - u u	data aniu	AEROSPACE
QA Closed:			Date:							· W	ork Order up	date only	
Work Orde	r:					DISPOSITION				AGAINST DE	PARTMENT	/PROCESS	
Part N NCR N	o					Rework Scrap Use-as-is Suspected Unapproved		Therm	Skid-tube Machining noforming Large Fab	Crosstube Small Fab Finishing Composite	4	Water Jet d. Eng. Coor. re/Packaging Supplier	Engineering Quality Other
Root		·		-	Desc	ription of work order update		nitial	Act	ion	Sign &		
Cause		Date	Step	Qty	·	or non-conformance	1	ief Eng	Descr	ription	Date	Verification	QC Inspector
Design Doc/Data Equip/Tooling Handling/Pre Material Operator Offset/Setup Process Supplier Training Transport Unapproved								J					
							FA	ULT CAT	regory				
Landin		iear Bending				General Bend	F		rogram		Outside Dim	ensions	Pressure/Forced
		Centre No Cracks Crimp/Kir Cuffs				BOM/Route Broken/Damage/Defect Burrs Contamination		1 .	ire ion Incomplete/Ui ions Incomplete/U	· —	Over/Under Part Incorre Part Lost/Mi Part Moved	cí 🗀	Set-up Temperature/Cure Weld Wrong Stock Pulled
		Crushing Heat Trea	a t			Countersink Cut Too Short		4	ned/off center	oncicui	Positioned V	· -	Other
		Inspection Marks/Ch	n Strip in	Tube		Drawing Drill Holes		Misread Off-set	d	L			adore in the second sec
		Turning S	equence		-	Finish Fit/Function		Out of	Calibration Sequence				

Picklist Print

Tuesday, July 29, 2014 2:29:15 PM

Work Order ID: 123046

123046

Parent Item:

D3589-15

D3589-15

Parent Item Name: Link

Start Date: 7/29/14

Required Date: 7/29/14

Start Qty: 4.00

Required Qty: 4.00

Comments:

IPP Rev:A 08-05-30 new issue DD verified by:ec

IPP Rev:B 09-

02-20 rev.b asper dwg DD verified by:EC

PER REV.C DD VERF:EC

IPP REV:C 12.07.23 AS

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Primary Item Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Status Issued
M304S16GA		Purchased	No		100	sf	608.0570	0.025	1		
M304S16	SGA							**			Dc 14/09/1

Location	Loc Qty	Loc Code	
MAT020	363.057		
M127821	71.317		
M129192	14.54		
M129449	277.2		· · · · · · · · · · · · · · · · · · ·
TPI	245		
M129545	245		

DQA:			Date:		·····								"DART
QA Closed:			Date:			WORK ORDER NON	-CC	ONFO	RMANCE / UP		ork Order up	date only	AEROSPACE
Q. (0,000 u.		·				DISPOSITION				AGAINST DE	PARTMENT	/PROCESS	
Work Orde	er: _					DISF 03111014	_		,	707.101.01	, , , , , , , , , , , , , , , , , , ,		_
						Rework			Skid-tube	Crosstube		Water Jet	Engineering
Part N	lo					Scrap			Machining	Small Fab	4	d. Eng. Coor.	Quality
						Use-as-is]	Thern	noforming	Finishing	Rec/Stor	e/Packaging	Other
NCR N	10.			****		Suspected Unapproved	J		Large Fab	Composite		Supplier	
Root					Desc	ription of work order update		nitial	Actio	on	Sign &		
Cause		Date	Step	Qty	l	or non-conformance	Ch	ief Eng	Descri	ption	Date	Verification	QC Inspector
Design													
Doc/Data									i	,			
Equip/Tooling													
Handling/Pre													
Material													
Operator													
Offset/Setup]				
Process													
Supplier													
Training	Ш					•							
Transport													
Unapproved			<u> </u>		<u> </u>								
							FA	ULT CA	TEGORY		·		
Landi	٣				_	General		1			7	. г	¬
	-	Bending			<u> </u>	Bend	<u> </u>	4	Program	<u> </u>	Outside Dim	-	Pressure/Forced
		Centre No	ot Concer	ntric	<u> </u>	BOM/Route	-	Grain		<u> </u>	Over/Under	F	Set-up
		Cracks			<u> </u>	Broken/Damage/Defect	<u> </u>	Hardwa		<u> </u>	Part Incorred	F	Temperature/Cure
	Ŀ	Crimp/Ki	nk/Ripple	/Wave	-	Burrs	-	4 '	tion Incomplete/Un	 	Part Lost/Mi	issing	Weld
		Cuffs				Contamination	_	_	tions Incomplete/U	nclear	Part Moved	L	Wrong Stock Pulled
		Crushing			<u> </u>	Countersink	_	7	gned/off center		Positioned V	· ·	Tout
		Heat Trea			\perp	Cut Too Short	_	Mislabe		L	Power Loss/	Surge [Other
	<u> </u>	Inspectio	-	Tube	_	Drawing	<u> </u>	Misrea					
	$ldsymbol{ld}}}}}}$	Marks/Ch			L	Drill Holes	<u>_</u>	Off-set					
		Turning S			\perp	Finish	_	-	Calibration				
1	1	Mave/Tw	vist in Tub	he	- 1	Fit/Function	1	IOut of	Sequence				


DART AEROSPACE LTD	Work Order:	123046
Description: Link	Part Number:	D3589-15
Inspection Dwg: D3589 Rev: C		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST


		AICHOLL III				
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø0.129	+0.005/-0.001	. 130	/		V=JKM-01	
Ø0.140	+0.005/-0.001	. 142	1			
0.900	+/-0.005	. 900	/			
0.38	+/-0.030	, 37	/			
1.28	+/-0.030	1.27	/			
0.063	+/-0.010	.060	J			
		<u> </u>				
		<u> </u>		ļ		
		<u> </u>				
			DAS 38			


			38		
Measured by:	pr/2	Audited by:	9-89	Preliminary Approval:	
Date:	14/09/11	Date:	14-9-12	Date:	

Rev	Date	Change	Revised by	Approved
A	09.05.07	New Issue	KJ/EC 10	
В	13.03.07	Dimensions revised per Dwg Rev C	KJ 🛠	<u> </u>
				•









R0.25 2 PL 1.13 REF 2.16 R4.90 С R0.16 2 PL 2.24 2.74 MAKE FROM D3589-7F D3589-7F AFT GUIDE PLATE FLAT PATTERN

0.45 **D3589-7 AFT GUIDE PLATE**

2 1 J

DESIGN DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA DRAWN DRAWING NO. CHECKED REV. C D3589 MFG. APPR. SHEET 5 OF 8 APPROVED TITLE \$ÇALE LATCH ASSEMBLY

COPYRIGHT © 2008 BY DART AEROSPACE LTD
THIS DOCAMON IS PRIMATE AND CONTROL HIS ABOUT ON THE OPPRESS CONTROL
THIS TOO CAME AND AND PRIMATE AND CONTROL HIS ABOUT ON THE OPPRESS CONTROL
THE TOTAL HIS AREA AND PRIMATE ON CONTROL HIS ABOUT ON THE OPPRESS HIS AREA
THE TOTAL HIS AREA AND PRIMATE AND PRIMATE TO DAY THOSE PERSON

INTO THE TOTAL HIS AREA AND PRIMATE AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO THE PERSON

THE TOTAL HIS AREA AND PRIMATE TO NTS DE APPR. DATE 12.07.04

D3589-7/-7F NOTES:


1) MATERIAL: AISI 304/316 STAINLESS STEEL SHEET, PER AMS 5513 OR AMS 5524, OR MIL-S-5059 (ANNEALED) 2B FINISH

16 GAUGE (0.063 THICK), (REF. DART SPEC M304S16GA)

2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: N/A
7) WEIGHT: 0.09 lbs


8

4



Ø0.129 THRU R0.18 -0.935 Ø0.250 THRU 0.063 R0.25 REF

D3589-13 LUG



3

. 2

D3589-15 LINK

D3589-13/-15 NOTES:

1) MATERIAL: AISI 304/316 STAINLESS STEEL SHEET, PER AMS 5513 OR AMS 5524, OR MIL-S-5059 (ANNEALED) 2B FINISH

16 GAUGE (0.083 THICK), (REF. DART SPEC M304S16GA) 2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: N/A
7) WEIGHT: 0.01 lbs EACH

8

DESIGN DART AEROSPACE LTD DRAWN HAWKESBURY, ONTARIO, CANADA DRAWING NO. CHECKED REV. C D3589 MFG. APPR. SHEET 7 OF 8 TITLE APPROVED SCALE LATCH ASSEMBLY DE APPR. DATE

